PRINTED: 09/15/2011 FORM APPROVED

		(X1) PROVIDER/SUPPLI IDENTIFICATION NO TN7505			(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - MAIN BUILDING 01 B. WING		(X3) DATE SURVEY COMPLETED	
NAME OF P	ROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	TATE, ZIP CODE			
NHC HEA	ALTHCARE, MURFRE	EESBORO		IVERSITY ST				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF CORI (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	COMPLETE DATE	
N 832	1200-8-608(2) Building Standards			N 832			· ]	
				The Maintenance Partner Inspected the resident room 217 bathroom and replaced the ceiling tile. The night light in room 233 was replaced to be working correctly. Weekly rounds will be done routinely to ensure the physical plant and nursing home environment will be maintained for the well-being and safety of the residents. The maintenance director will monitor the building on an ongoing basis.	<del>-9/12/11</del> .	9/13/11		
							į	
sion of He	alth Care Facilities	olon-	00 p. 1		O TITLE	/	(XG) DATE	

STATE FORM

IGV121